

SECTION VIII – CONTROL MEASURES

Respiratory Protection:	Use NIOSH approved dust mask respirator for prolonged grinding or cutting if dusty conditions exist.
Ventilation:	Use sufficient local exhaust to reduce the dust to PEI for respirable silica when grinding or dry sawing.
Protective Gloves:	Not required.
Eye Protection:	Wear safety glasses to protect eyes from dust particles.

This MSDS was prepared on 5/27/04 – J. Guthrie Manager, Material Safety

DISCLAIMER

The information and recommendations contained herein are offered as a service to our customers but are not intended to relive the user of his responsibility to investigate and understand other pertinent sources of information and to comply with all laws and procedures applicable to the safe handling and use of these products. The information and recommendations provided herein were believed to be generally reliable. However, ABT, Inc., makes no warranty concerning their accuracy and ABT, Inc. will not be liable for claims relating to any party's use or reliance on information or recommendations contained herein, regardless of whether it is claimed that the information or recommendations are inaccurate, incomplete or otherwise misleading.

This MSDS was prepared on 5/27/04 by J. Guthrie, Manager, Material Safety.